

## MECHANICAL REPAIRS RISK ASSESSMENT

### CSC Fleet Services Ltd

45 Arlington Way Meir Park Stoke on Trent ST3 7WH

Location: Third Party Client Site

<b>Title :Mobile Engineers working at various sites</b>	<b>Date of Assessment : 1/05/2025</b>	<b>Risk Assessor : Chris Card</b>
<b>Risk Assessment Reference : CSC</b>	<b>People involved in making this assessment : Chris Card</b>	
<b>Task/ Process : Engineers Carrying out curtain repairs</b>	<b>People at Risk : Employees, Contractors, Members of the Public, Client Personnel, Visitors</b>	
<b>Hazard : Contact with moving or rotating parts Risk: Cut's Broken bones</b>		
<b>Control Measures:</b>		
SSOW to be followed at all times		
Only trained individuals to use the equipment		
No loose clothing or jewellery to be worn when operating equipment		
A trained first aider on site at all times		
Check equipment before use		
110 volt equipment to be used		
Make sure all equipment is PAT tested		
Correct PPE to be worn at all times		
<b>Hazard : Been hit by ejected debris Risk: Damage to eye's Cut's ,Broken bones</b>		
<b>Control Measures:</b>		
SSOW to be followed at all times		
Correct PPE to be worn at all times		
The individual is trained to use the equipment		

Guards to be fitted to the equipment when possible

A trained first aider on site at all times

**Hazard : Manual handling of heavy objects Risk: Back injury, Trapping of toes,fingers**

**Control Measures:**

SSOW must be followed at all times

Correct PPE must be worn at all times

Any heavy objects must be used to move heavy objects

Ask for assistance where possible

Trained first aider on site at all times

All staff to be trained in lifting techniques

Work area to be kept clean at all times

**Hazard : Fire Risk: Burns ,Death, Property damage**

**Control Measures:**

SSOW must be followed at all times

Correct PPE must be worn

Switch equipment off after use

110 volt equipment to be used

Staff are trained up before using equipment

All staff know where fire assembly points are located

Fire extinguishers are in service and on site

Keep all flammable sources away from the work area

**Documents Associated with this Risk Assessment:**

**Review Date :** 1/05/2025

**Reviewer :**Chris Card

**C**

