

COSHH RISK ASSESSMENT

CSC Fleet Services Ltd

45 Arlington Way Meir Park Stoke on Trent ST3 7WH

Location: Third Party Client Site

Title :Mobile Engineers working at various sites	Date of Assessment : 1/05/25	Risk Assessor : Chris Card
Risk Assessment Reference : CSC	People involved in making this assessment : Chris Card	
Task/ Process : Engineers Carrying out curtain repairs	People at Risk : Employees, Contractors, Members of the Public, Client Personnel, Visitors	
Hazard : GT 85 SPRAY LUBE Risk : Flammable		
Control Measures:		
<ul style="list-style-type: none"> • Do not pierce. • If contact with skin wash with water. • If contact with eyes rinse with water. • Ensure adequate ventilation when using. • Keep away from sources of ignition 		
Hazard : Propane Risk : Highly Flammable		
Controlled Measures		
<ul style="list-style-type: none"> • Store cylinders outside in metal locked cage. • Store away from naked flames • Store away from combustibles • Avoid Inhalation of vapour 		
Hazard : Screen wash Risk : Flammable, irritating skin		
Controlled Measures		
<ul style="list-style-type: none"> • Follow manufacturer's instructions. • Handle carefully ensuring not to spill or splash. • If prolonged use ensure PPE is worn • If contact with skin, wash immediately with soap and water. 		

Hazard : De-icer Risk : Flammable

Controlled Measures

- Follow manufacturer's instructions.
- Handle carefully ensuring not to spill or splash.
- Avoid excessive use in confined space.
- If prolonged use ensure PPE is worn
- If contact with skin, wash with soap and water
- Store in accordance with manufacturer's instructions.

Hazard : Engine oil Risk : Skin irritation

Control Measures

- Oil is manually pumped from oil drum in to HGV oil tank. Skin contact is kept to a minimum although some minor exposure from drips and residue is possible.
- Chemical resistant gloves to be used when topping up oil.
- Prevent from spreading (e.g. by damming-in or oil barriers).
- Do not allow to penetrate the ground/soil.
- Do not allow to enter sewers/ surface or ground water.

Hazard : Hydraulic oil Risk : Skin irritation

Control Measures

- Oil is manually pumped from oil drum in to Hydraulic deck oil tank. Skin contact is kept to a minimum although some minor exposure from drips and residue is possible.
- Chemical resistant gloves to be used when topping up oil.
- Prevent from spreading (e.g. by damming-in or oil barriers).
- Do not allow to penetrate the ground/soil.

- Do not allow to enter sewers/ surface or ground water.

Documents Associated with this Risk Assessment:

--

Review Date : 01/05/26

Reviewer :Chris Card

